Each

Dart Aerospace Ltd. Thursday, 06/12/2007 7:02:52 AM User: Linda Lacelle **Process Sheet** : D3332-041 : CC-DAR01 Dart Aerospace Ltd. **Drawing Name** Customer Job Number : 36163 **Estimate Number** : D3332041 **Part Number** P.O. Number : REPAINT **Drawing Number** This Issue : 06/12/2007 NU: **Project Number** Prsht Rev. : MACHINED PARTS **Drawing Revision** First Issue Type : MA Material : 00015 **Previous Run** 10 Um: : 12/12/2007 Qty: **Due Date** Written By Checked & Approved By Comment **Additional Product** Job Number: Description: Seq. #: Machine Or Operation: HAND FINISHING RESOURCE #1 1.0 Comment: HAND FINISHING RESOURCE #1 **PULL FROM STK:** 10 X D3332-041 B35441 D3332041 Pin Assembly 2.0 Comment: Qty.: 1.0000 Each(s)/Unit Total: 10.0000 Each(s) Pin Assembly POWDER COATING 3.0 POWDER COATING Comment: POWDER COATING MASK ALL PARTS, PAINT D3332-3 FIRE RED PER DRWG D3332 REV.A INSPECT POWDER COAT/CHEMICAL CONVERSION 4.0 QC3 Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION PACKAGING 1 PACKAGING RESOURCE #1 5.0

Page 1

Comment: PACKAGING RESOURCE #1

RE-IDENTIFY USING NEW B/N

Usêr:

 Thursday, 06/12/2007 7:02:52 AM Linda Lacelle

Process Sheet

Customer: CC-DAR01 Dart Aerospace Ltd.

Drawing Name: D3332-041

Job Number: 36163

Part Number: D3332041

Job Number:



Seq. #:

Machine Or Operation:

Description:

6.0

QC21

FINAL INSPECTION/W/O RELEASE



Do7/10/13

Comment: FINAL INSPECTION/W/O RELEASE

Job Completion





nin 2007 (n/12





,	·	!				
	DESIGN		DRAWN	BY	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
	CHECKED		APPROVED		DRAWING NO. D3332	REV. A
	存					SHEET 1 OF 4
	DATE				TITLE	SCALE
	04.12.14				PIN ASSEMBLY	1:2
	Α	04.12.14			NEW ISSUE	
	Al		P 05.	07,04	0.080 WAS 0.050; ABB TOLELANCE	+0,000 -0,005





D3332-043 PIN ASSEMBLY

NOTES:

- 1) POSITION PARTS USING D3332-041T1
 2) WELD PER DART QSI 004
 3) MASK THREADS PRIOR PAINTING
 4) FINISH: POWDER COAT FIRE RED (REF. 4.3.5.10) PER QSI 005 4.3
 (COVER THREAD ONLY FOR D3332-5/-9 PRIOR PAINTING)
 5) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED
 6) ALL DIMENSIONS ARE IN INCHES
 7) BREAK ALL SHARP EDGES. 0.005 TO 0.10